




Inside Mount, With or Without Window Frame or Moulding

- **WIDTH:**
Measure the inside width of the window in 3 separate places- across the top, center and bottom between casings; use the smallest measurement.
- **HEIGHT:**
Measure the inside height in 3 separate places-vertically down the left, center and right of the opening. Use the smallest measurement. (The factory will deduct 1/8" top, bottom, left and right for clearance on all inside mounts.)



Measure 3 times across the top and the bottom.

Your measurements are for quoting purposes only.

We will measure your windows for final production.

ShutterUp.com

sales@shutterup.com

1-877-708-1749

Fax (941) 296-7489